



WHAT IS YOUR C-ARM HIDING FROM YOU?



Fluoroscopic image distortion cannot be detected with the naked eye and could potentially influence surgeon's intra-operative decisions.

This may lead to alignment issues such as:

Decreased stability, leg length discrepancies & incorrect component positioning

OrthoGrid's HipGrid® and PhantomMSK™ Hip:

Reveal hidden fluoroscopic distortion

Easily integrate into current surgical workflow

Interfaces with existing hospital or ASC equipment

Open platform – compatible with all implant systems

Cost effective solution for anatomical alignment

NO COST | NO OBLIGATION

***PATIENT REQUESTED
FAST TRACK TRIAL***

OrthoGrid.com/contact or 801.703.5866

